

# LITON LIGHTING

## INSTALLATION OPERATION INSTRUCTIONS

### PREPARING THE LUMINAIRE

U.L. Listed

- 1. WARNING** - Before starting the installation, disconnect the power by turning off the circuit breaker or removing the fuse at the fuse box. Turning the power off using the light switch is not sufficient to prevent electrical shock.
2. If you are replacing an existing Luminaire, disconnect and remove the old luminaire. Expose the supply electrical wires to make connections.
3. Place the Luminaire Canopy to the Ceiling and fasten the Mounting Bracket to the Outlet Box (by others), using 8-32 machine screws (provided) as shown in illustration .
4. Make electrical connections: Connect grounding wire (green or bare copper) from the supply circuit to the green or bare copper wire from the luminaire. Connect the white wire(s) from the luminaire to the white wire of the supply circuit. Connect the black wire(s) from the luminaire to the black wire of the supply circuit. Use U.L. Listed wire connectors (by others). Secure wire connectors with U.L. Listed electrical tape (by others).
5. Place Luminaire Canopy to the Ceiling surface allowing the Mounting Bracket fits in; then align the holes and fasten the Canopy using the two mounting screws as shown in illustration.
6. Install the lamp(s) (by others) Do Not Exceed Recommended Wattage

NOTE: See lamp shade lable for proper lamp and wattage. **DO NOT EXCEED**

## **SURFACE PENDALIER SERIES**

SURFACE LUMINAIRE  
- CEILING MOUNT-

